




www.franke.com




1



| Model      |  | E   | F   | r3 | Model         | E | F   | r3  |    |
|------------|--|-----|-----|----|---------------|---|-----|-----|----|
| MRX 110 19 |  | 190 | 400 | 16 | MRX 110 55    |   | 550 | 400 | 16 |
| MRX 110 34 |  | 340 | 400 | 16 | MRX 110 70    |   | 700 | 400 | 16 |
| MRX 110 40 |  | 400 | 400 | 16 | MRX 160 34-19 |   | 555 | 400 | 16 |
| MRX 110 45 |  | 450 | 400 | 16 | MRX 120 34-34 |   | 705 | 400 | 16 |
| MRX 110 50 |  | 500 | 400 | 16 | MRX 120 40-40 |   | 825 | 400 | 16 |



2



3

MRX 110 19 -  
MRX 110 55



MRX 110 70 -  
MRX 120 40-40

